



CONDITION BASED SERVICE (CBS).

BRAKE FLUID.



- Replace brake fluid



THE 1

| | |
|-----------------------|-----------|
| BMW F20 (116d ED LCI) | MUR 3,551 |
| BMW F20 (118i LCI) | MUR 3,804 |
| BMW F20 (116i, 118i) | MUR 3,551 |
| BMW F40 (118i) | MUR 3,298 |

THE 2

| | |
|----------------|-----------|
| BMW F44 (218i) | MUR 3,298 |
| BMW F45 (218i) | MUR 3,551 |

THE 3

| | |
|----------------------|-----------|
| BMW F30 (318i LCI) | MUR 3,804 |
| BMW F30 (320i LCI) | MUR 3,804 |
| BMW F30 (330i LCI) | MUR 3,804 |
| BMW F30 (316i) | MUR 3,804 |
| BMW F30 (320i ED) | MUR 3,804 |
| BMW F30 (320i, 328i) | MUR 3,804 |
| BMW G20 (330i) | MUR 3,804 |
| BMW G20 (330e) | MUR 3,298 |

BMW i3

| | |
|-------------------------|-----------|
| BMW i3 Series I01 (i3) | MUR 3,298 |
| BMW i3 Series I01 (i3S) | MUR 3,298 |

THE 4 | THE i4

| | |
|------------------|-----------|
| BMW F3X (420i) | MUR 3,804 |
| BMW G22 (430i) | MUR 3,298 |
| BMW G26 (i4 M50) | MUR 3,804 |
| BMW G26 (i4 40) | MUR 3,804 |

THE 5

| | |
|------------------------------|-----------|
| BMW G30 (520i) | MUR 3,298 |
| BMW G30 (530i, 530e) | MUR 3,298 |
| BMW G30 (520i LCI, 530e LCI) | MUR 3,298 |

THE 7 | THE i7

| | |
|----------------------|-----------|
| BMW G11 (740e) | MUR 4,563 |
| BMW G12 (740e) | MUR 4,563 |
| BMW G12 (745LeX LCI) | MUR 4,563 |
| BMW G70 (60) | MUR 4,460 |

THE X1 | THE iX1

| | |
|-------------------------|-----------|
| BMW F48 (18i, 20i) | MUR 3,551 |
| BMW F48 (18i LCI) | MUR 3,298 |
| BMW F48 (25eX LCI) | MUR 3,298 |
| BMW U11 (18i, 20i, 23i) | MUR 4,057 |
| BMW U11 (25e) | MUR 3,804 |
| BMW U11 (BEV) | MUR 3,804 |

THE X2

| | |
|--------------------|-----------|
| BMW F39 (18i, 20i) | MUR 4,310 |
| BMW F39 (25eX LCI) | MUR 3,298 |

THE X3 | THE iX3

| | |
|------------------------------|-----------|
| BMW F25 (28i N52, 28i N20) | MUR 3,298 |
| BMW G01 (20i, 30i) | MUR 3,298 |
| BMW G01 (20iX LCI, 30eX LCI) | MUR 3,298 |
| BMW G01 (30e) | MUR 3,298 |
| BMW G01 (M40i) | MUR 3,298 |
| BMW F25 (20d) | MUR 3,062 |
| BMW F25 (30d) | MUR 2,850 |
| BMW G08 (BEV LCI) | MUR 4,563 |

THE X4

| | |
|------------------------------|-----------|
| BMW F26 (20ix) | MUR 3,214 |
| BMW F26 (28ix) | MUR 3,298 |
| BMW G02 (20i, 30i, 20iX LCI) | MUR 3,298 |

THE X5

| | |
|----------------------|-----------|
| BMW F15 (40e) | MUR 4,057 |
| BMW F15 (25dx, 30dx) | MUR 3,298 |
| BMW G05 (40i) | MUR 4,057 |
| BMW G05 (30dx, M50d) | MUR 3,298 |
| BMW G05 (45e) | MUR 4,563 |

THE X6

| | |
|----------------------|-----------|
| BMW F16 (30dx, 40dx) | MUR 3,954 |
| BMW G06 (40iX) | MUR 4,563 |

THE X6

| | |
|----------------|-----------|
| BMW I20 (40ix) | MUR 4,816 |
| BMW I20 (50ix) | MUR 3,804 |

Price includes: Materials, Labour and VAT. Exchange rate: MUR 49 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.2023