



# CONDITION BASED SERVICE (CBS).

## SPARK PLUGS.



- Replace spark plugs.
- To ensure optimum performance, fuel economy and low emissions.



### THE 1

|                    |           |
|--------------------|-----------|
| BMW F20 (116i)     | MUR 8,194 |
| BMW F20 (118i LCI) | MUR 8,930 |
| BMW F20 (118i)     | MUR 8,447 |
| BMW F40 (118i)     | MUR 8,447 |

### THE 2

|                |           |
|----------------|-----------|
| BMW F44 (218i) | MUR 8,447 |
| BMW F45 (218i) | MUR 7,159 |

### THE 3

|                      |            |
|----------------------|------------|
| BMW F30 (318i LCI)   | MUR 8,930  |
| BMW F30 (320i LCI)   | MUR 10,425 |
| BMW F30 (330i LCI)   | MUR 10,425 |
| BMW F30 (316i)       | MUR 8,700  |
| BMW F30 (320i ED)    | MUR 9,965  |
| BMW F30 (320i, 328i) | MUR 9,965  |
| BMW G20 (330i)       | MUR 9,965  |
| BMW G20 (330e)       | MUR 8,447  |

### BMW i3

|                        |           |
|------------------------|-----------|
| BMW i3 Series I01 (i3) | MUR 6,285 |
|------------------------|-----------|

### THE 4 | THE i4

|                |           |
|----------------|-----------|
| BMW F3X (420i) | MUR 9,965 |
| BMW G22 (430i) | MUR 8,447 |

### THE 5

|                              |           |
|------------------------------|-----------|
| BMW G30 (520i)               | MUR 8,970 |
| BMW G30 (530i, 530e)         | MUR 8,970 |
| BMW G30 (520i LCI, 530e LCI) | MUR 8,447 |

### THE 7 | THE i7

|                      |           |
|----------------------|-----------|
| BMW G11 (740e)       | MUR 9,160 |
| BMW G12 (740e)       | MUR 9,160 |
| BMW G12 (745LeX LCI) | MUR 8,700 |

### THE X1 | THE iX1

|                    |           |
|--------------------|-----------|
| BMW F48 (18i, 20i) | MUR 7,159 |
| BMW F48 (18i LCI)  | MUR 8,447 |
| BMW F48 (25eX LCI) | MUR 8,907 |
| BMW U11 (18i, 20i) | MUR 6,814 |
| BMW U11 (25e)      | MUR 6,814 |
| BMW U11 (23i)      | MUR 8,447 |

### THE X2

|                    |           |
|--------------------|-----------|
| BMW F39 (18i)      | MUR 7,067 |
| BMW F39 (20i)      | MUR 8,447 |
| BMW F39 (25eX LCI) | MUR 8,907 |

### THE X3 | THE iX3

|                              |            |
|------------------------------|------------|
| BMW F25 (28i N52)            | MUR 11,460 |
| BMW F25 (28i N20)            | MUR 8,700  |
| BMW G01 (20i, 30i)           | MUR 8,907  |
| BMW G01 (20iX LCI, 30eX LCI) | MUR 8,447  |
| BMW G01 (30e)                | MUR 8,447  |
| BMW G01 (M40i)               | MUR 8,700  |

### THE X4

|                    |           |
|--------------------|-----------|
| BMW F26 (20ix)     | MUR 8,447 |
| BMW F26 (28ix)     | MUR 8,700 |
| BMW G02 (20i)      | MUR 8,907 |
| BMW G02 (30i)      | MUR 8,907 |
| BMW G02 (20iX LCI) | MUR 8,447 |

### THE X5

|               |           |
|---------------|-----------|
| BMW F15 (40e) | MUR 8,447 |
| BMW G05 (40i) | MUR 8,447 |
| BMW G05 (45e) | MUR 8,700 |

### THE X6

|                |           |
|----------------|-----------|
| BMW G06 (40iX) | MUR 8,700 |
|----------------|-----------|

Price includes: Materials, Labour and VAT. Exchange rate: MUR 49 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.2023